



1 = ADJ, 2= OUT, 3= IN

- U1 will limit the charge current to about 1.5 Amps
- U2 will adjust the charge voltage.
- Set the 5K pot for about 10 - 12 Volts
- C4 is 1.8 Farads or larger
- The + & - Out should be heavy duty but flexible cables
- The + and - Out tips should be heavy duty copper

OL Communications, Inc.		
Battery Tab Welder		
Joe Loucka	Rev 1.0	Page 1
	3/21/2010	